


# **MECH 211 – Mechanical Engineering Drawing**

François Tardy


Credits: 3.5

## **Lecture 9**


# Content of the lecture

- Dimensions
  - Nomenclatures
  - Dimensioning practices
  - Dimensioning examples
  - Dimensioning rules
    - Aligned dimensions
    - Dimensions outside the view
    - The extension line practice
    - The centerline
- 

# Content of the lecture

- Radial and diametrical dimensions
  - Chained features
  - Explanations
  - Not to scale designations
  - Reference of the extension lines
  - General dimensioning
  - Contour dimensioning
  - Size vs. location
- 

# Life of Engineers




# Dimensions

Dimensions are the numerical value that define the size, shape, location, surface texture, or geometric characteristic of a feature.

What should be defined before dimensioning?

- Perfect understanding of the shapes
- Units
- Minimizing the data to geometrically define the part
- Features to be defined
- Dimensioning rules



Start with a base of reference.




# Dimensions – cont'd

- Shape, location, relative position of features in one part.
- Locate the position of the tool with respect to the blank – manufacturing hints
- Feature sizes (dimensions: linear, angular)
- Position or location (linear, angular)





# Nomenclature

- **Dimension:** A numerical value which defines size or relative position.
  - **Basic dimension:** Theoretically exact size of the feature.
  - **Reference dimension:** Dimension not direct used, but indicated.
  - **Dimension line:** Line that shows the extent and the direction of the feature.
  - **Arrow:** Symbol @ the end of dimension lines.
- 

# Nomenclature cont'd

**Extension line:** Line that shows which feature is associated with the size

**Visible gap:** Gap between corners of the feature and extension lines


**Leader line:** Extension line that shows the size of a inaccessible feature

**Diameter/Radius symbols:** d/r followed by a number, the size of the feature


**Datum:** A reference line/surface for datum dimensioning.

# Dimensioning Practice

- Texts are 3mm or 0.125" high
- The space between lines of text is 1.5 mm or 0.0625"



Millimeter dimensioning






Decimal dimensioning

# Dimensioning Practice

## REMEMBER

Sizes and dimensions are used for manufacture purposes



# Dimensioning Practice – cont'd

## Size dimensions


1. Horizontal
2. Vertical
3. Diameter
4. Radius

## Position dimensions


- Horizontal position
- Vertical position
- Angle

- Standard practice in dimensioning – **promotion of clarity.**
- Make sure that the part can be built to dimensions.
- The provided dimensions must be measurable.

# Dimensioning Example




Symbol	A	B
Hole diameter	20	10



Tabular dimensioning

# Dimensioning Example

## Coordinate Dimensioning



Hole	X	Y	Size
A1	-1.00	2.00	Ø.50
A2	-1.00	-.50	Ø.50
A3	1.10	-.50	Ø.50
A4	0	0	Ø.50
A5	3.38	0	Ø.50
A6	3.38	2.62	Ø.50
B1	1.50	2.62	Ø.25
B2	1.50	1.50	Ø.25
B3	2.88	1.50	Ø.25

# Dimensioning Rules

- Each feature of an object is dimensioned once and only once.
- Dimensions should be selected to suit the function of the object.
- Dimensions should be placed in the most descriptive view of the feature being dimensioned.
- Dimensions should specify only the size of a feature. The manufacturing method should only be specified if it is a mandatory design requirement.
- Angles shown on drawings as right angles are assumed to be 90 degrees unless otherwise specified, and they need not be dimensioned.

# Dimensioning Rules cont'd

- Dimensions should be located outside the boundaries of the object whenever possible.
- Dimension lines should be aligned and grouped where possible to promote clarity and uniform appearance.
- Crossed dimension lines should be avoided whenever possible. When dimension lines must cross, they should be unbroken.
- The space between the first dimension line and the object should be at least  $\frac{3}{8}$  inch (10mm). The space between dimension lines should be at least  $\frac{1}{4}$  inch (6mm).
- There should be a visible gap between the object and the origin of an extension line.

# Dimensioning Rules cont'd


- Extension lines should extend 1/8 inch (3mm) beyond the last dimension line.
- Extension lines should be broken if they cross or are close to arrowheads.
- Leader lines used to dimension circles or arcs should be radial.
- Dimensions should be oriented to be read from the bottom of the drawing.
- Diameters are dimensioned with a numerical value preceded by the diameter symbol.

# Dimensioning Rules cont'd


- Concentric circles should be dimensioned in a longitudinal view whenever possible.
- Radii are dimensioned with a numerical value preceded by the radius symbol.
- When a dimension is given to the center of an arc or radius, a small cross is shown at the center.
- The depth of a blind hole may be specified in a note. The depth is measured from the surface of the object to the deepest point where the hole still measures a full diameter in width.
- Counterbored, spotfaced, or countersunk holes should be specified in a note.

# Aligned Dimensions

Aligned Dimensions have text placed parallel to the dimension line, with vertical dimensions read from the right of the drawing.




Unidirectional  
Current standard




Aligned  
Old standard

# Dimension Outside the View




(A)  
Avoid







(B)  
Good Practice

# Extension Line Practice



# Extension Line Practice

- Use any of the four methods, as long as they are readable.
- Stagger dimensions when grouping.
- Do not break dimension lines for object lines.




(a)

(b)



# The Center Line Practice

Centerline used as  
an extension line





# Radial and Diametrical Dimensions

- More than half a circle: **diameter**
- Less than half a circle: **radius**
- Leaders to point towards centre of the circle or arc (Radial)




# Dimensioning Arcs


- Arcs are dimensioned in a view where a true shape is seen.
- The leader and the value are located inside the arc if space is available. If not, the value is moved out with or without the leader.
- A cross indicates the centre of all arcs with or without dimensions, except for small and unimportant radii.
- False center with jogged leader can be used for long radii.



# Dimensioning of Chained Features




Staggering dimension text



Aligning dimension lines


# Detailed Explanations

Extension lines and line indicators are used to detail manufacturing requirements.




# Not to Scale Designation

- All features in drawings are scaled accordingly
- Unscaled features could be also represented and indicated.




# Reference for the Extension Line

- Dimensioning is always done between crisp surfaces.
- Sometimes, such surfaces are not available and dimensions are indicated to facilitate the manufacturing process.




# General Dimensioning

Holes should be dimensioned in the view in which they are best seen.




# General Dimensioning cont'd

Features should be dimensioned in the views in which they are best seen.



# General Dimensioning cont'd

Do not draw a view/section for a feature that could be indicated by a symbol.




Counterbore or spotface symbol



Countersink symbol





Diameter symbol




Square symbol



Depth symbol




# General Dimensioning – Cont'd



Counterbore

Countersunk


Spotface



A section view is not necessary as symbols in the top view indicate these shapes.

# General Dimensioning – cont'd




- Dimension keyseats from the bottom of the keyseat to opposite end of the shaft.
- For key seat, from top of keyway to bottom of hole.



**Keyseat and keyway**

# General Dimensioning – cont'd





- Dimension by giving centre to centre distances and radii of ends.
- Only one radius dimension is required, but the amount of instances must be mentioned.



**Slot cuts**

# General Dimensioning cont'd



## Chamfers



# General Dimensioning cont'd

## Concentric circles





- Dimensioned in the longitudinal view.



# General Dimensioning cont'd




## Grooves

Dimensioned with local notes or by showing the dimensions of the **undercut depth** and the **distance**.









# General Dimensioning - cont'd

- Threads are dimensioned with local notes.
- Internal or tapped threads are shown on the circular view.
- External threads are shown on the longitudinal view.





# Contour Dimensioning





# Size vs. Location

Both size and location dimensions have to be provided to avoid any confusion








# Size vs. Location





# Superfluous Dimensions





# Creating a Dimensioned Drawing





Step 1



Step 2




Step 3




Step 4

# Representation Standards – ANSI Y 14.5 M


## New standard




## Old standard




# REMINDER

- Each feature of an object is dimensioned once and only once.
  - The location and/or size dimensions for a feature should be placed in the view in which that feature is most clearly seen i.e. where its shape description is most complete.
  - Any dimension specified should correspond to a range of dimensions in the final product, i.e. each dimension should include an appropriate tolerance
- 

# REMINDER

- Dimension lines should never coincide with object lines or other extension lines,
  - Dimension lines should be unbroken except for the number between the arrowheads,
  - There should be a visible gap between the object and the origin of an extension line,
  - Crossing of dimension lines should be avoided wherever possible.
- 

# REMINDER

- Dimensions should reference object lines rather than hidden lines,
  - Dimensions should be placed in spaces as close as possible to their point of application,
  - When dimensions are "nested", the smaller dimension should be placed closer to the object to avoid unnecessary crossing,
  - Dimensions should be located outside the boundaries of the object wherever possible.
- 

# Working Drawings



- Used to describe all the necessary details that enable the fabrication of the component,
- Use the necessary views and sections,
- Provide all the necessary dimensions only in one single location.












# Problems

Draw all the necessary views/sections that would enable the correct dimensioning of the following parts:







Dimensional, Geometric and Position Tolerances

# **TOLERANCING**




# Tolerancing Basics

**Tolerance:** undesired but accepted abatement form a basic size or shape.

There are three types of tolerances:

- Dimensional tolerances (limits of the linear or angular dimensions)
- Positional tolerances (limits of linear or angular location of features within a part)
- Geometric tolerances (abatement form shape or position of a specific feature)


# Fundamentals

- Undesired but permitted dimensional variations of a certain feature due to economics aspects in manufacturing.
  - Tolerances are essential when two or more parts are assembled together (clearance).
  - Permitted variations are related to the functions of the parts.
- 




.497 Upper Limit (MC)  
 .495 Lower Limit (LMC)


.502 Upper Limit (LMC)  
 .498 Lower Limit (MMC)



Engineering Dimensioned Drawing



Machined Part



MMC – Maximum Material Condition


LMC – Least Material Condition

# What is Important?

- Understanding tolerances,
- Selection and calculation,
- Prescription of tolerances,
- **Tolerance of a size:** the difference between the maximum and the minimum allowed size of the specific dimension.



# Nomenclature

- **Nominal size:** the general size
  - **Basic size:** theoretical size
  - **Actual size:** the measured size
  - **Limits:** the max and min sizes shown by the tolerance
  - **Allowance:** for mating parts – min clearance or max interference
  - **Tolerance:** total allowable variance
- 

# Nomenclature

- **Maximum material condition (MMC)** - condition of the part to contain max amount of material
- **Least material conditions (LMC)** - condition of the part to contain the min amount of material
- **Clearance fit** - condition of a fit that enables space between parts
- **Interference fit** - condition of a fit that enables no space between the two mating parts
- **Transition fit** - clearance or interference fit

# Tolerance Representation

## Direct limits

(limit dimensioning)

## Tolerance value

(plus or minus dimension)

## Unilateral Tolerances


(only in one direction from basic size)

## Specific note


(\* dimension  $\phi 2 \pm 0.001$ )

## General note

(All diameters  $\phi 2 \pm 0.001$ )




(A) Direct limits




(B) Tolerance values

# Clearance and Interference




Allowance always equals smallest hole minus largest shaft

# Transition Fit




# How to Determine the Fits?

Evaluate the allowance and the interference




# Functional Dimensioning

- Functional dimensioning begins with tolerancing the most important features.
- The functionality of the assembly has to be very clearly established by the designer.
- The assembly procedure as well as the manufacturing processes involved in producing the part must be also clear to the designer.
- Tolerances should be as “coarse” as possible and still permit the satisfactory use of the part – Why?



Functional dimensioning  
Step 1




Functional dimensioning  
Step 2

# Tolerance Stack-up


- Tolerances taken in the same direction from one point of reference are additive
  - tolerance stack-up
- Tolerance stack-up can be eliminated with the careful selection and placement of dimensions.




# Tolerance Stack-up may cause assembly problems





PART A




PARTS A and B  
assembled





PART B







PART A




PART B



Dimensioning with respect to the base would help




PART A




$XX \pm .005$

$XX \pm .005$

$XX \pm .005$



PART B




$XX \pm .005$


$XX \pm .005$

$XX \pm .005$

Providing tolerances for the locating dimensions is a better solution







A




B

Which of the two dimensioned features is better for assembly purposes?


# Tolerancing in ISO



# The Metric Preferred Hole-Based System of Fits



# Line Form vs. Note Form Tolerancing




Hole
40.025
40.000
<hr/>
.025

Hole tolerance

Shaft
39.991
39.975
<hr/>
.016

Shaft tolerance







Hole
40.025
40.000
<hr/>
.025

Tightest fit

Shaft
39.991
39.975
<hr/>
.016


Loosest fit

# Standard Representation of Metric Tolerances



# Basic Hole and Shaft System

## Imperial Size



Interference fit

Clearance fit


Clearance fit

Interference fit

**Basic hole system**

**Basic shaft system**

# RUN FIT



0.500 is the smallest hole  
0.496 is the largest shaft  
0.004 is the tightest fit

0.503 is the largest hole  
0.493 is the smallest shaft  
0.10 is the loosest fit

0.500 is the lower limit hole  
0.496 is the upper limit shaft  
0.004 is the ALLOWANCE



0.496 is the upper limit shaft  
0.003 is the shaft tolerance  
0.493 is the LOWER LIMIT SHAFT

0.500 is the lower limit hole  
0.003 is the hole tolerance  
0.503 is the UPPER LIMIT HOLE



# Sample Dimensioning Problems




(1)





(2)




(3)



(4)




(5)




(6)

# Tolerancing Sample Problem



\* See appendix for American Standard Socket-head Shoulder Screw



Bushing




Housing

Limits of size		1	2 - FN 4 fit
Hole	Nominal size	.500	.750
	$\pm$ Limit	$\pm$	$\pm$
	= Upper limit	=	=
	Nominal size	.500	.750
	+ Limit	+	+
	= Lower limit	=	=
Shaft	Nominal size	.500	.750
	$\pm$ Limit	$\pm$	$\pm$
	= Upper limit	=	=
	Nominal size	.500	.750
	$\pm$ Limit	$\pm$	$\pm$
	= Lower limit	=	=
Limits of fit	Smallest hole		
	- Largest shaft	-	-
	= Tightest fit	=	=
	Largest hole		
	- Smallest shaft	-	-
	= Loosest fit	=	=



# Geometric Tolerancing

Used to limit the abatement in the geometric variation of features.



# Feature Control Frames Example







































//	.010	A
----	------	---




1.XX  
○ .010




# Dimensioning and Tolerancing Symbols

					
Datum feature	Datum target	Target point	Concentricity	Circularity	MMC
					
LMC	RFS	Projected tolerance zone	Parallelism	Flatness	Cylindricity
					
Diameter	Position	All around (profile) (ISO-none)	Profile surface	Profile line	Straightness
					
Perpendicularity	Angularity	Runout circular	Runout total	Counterbore or spotface (ISO-none)	
					
Countersink (ISO-none)	Depth (or depth) (ISO-none)	Dimension origin	Critical taper	Square (enaps)	
					
Reference	Arc length (ISO-none)	Slope	Times, times or by	Radius	
					
Spherical radius (ISO-none)	Spherical diameter (ISO-none)	Feature control frame		Symmetry (ISO-only)	
					
Dimension not to scale	Miscellaneous symbols				


# Axis Straightness




FFS Basis




MMC Modified



Drawing




Effect  
(scale enlarged)




Inspection  
Methods


# Roundness



Drawing




Tolerance Zone




Inspection Method  
(check only one slice at a time)


# Cylindricity



Drawing




Effect




Inspection Method

# Bracket with GT Example




# Drawing with GT Example



# Think Practical

when approaching a design problem



**"You were right ... we should have built a raft."**