


CHP 4: IMPERFECTIONS IN SOLIDS

ISSUES TO ADDRESS...

- What are the solidification mechanisms?
- What types of defects arise in solids?
- Can the number and type of defects be varied and controlled?
- How do defects affect material properties?
- Are defects undesirable?


Imperfections in Solids

- **Solidification**- result of casting of molten material
 - 2 steps
 - Nuclei **form**
 - Nuclei **grow** to form crystals – grain structure
- Start with a molten material – all liquid



- Crystals grow until they meet each other


Types of Imperfections

- Vacancy atoms
 - Interstitial atoms
 - Substitutional atoms
- 
- Point defects
- Dislocations ————— Line defects
 - Grain Boundaries ————— Area defects

Point Defects


- **Vacancies:**

-vacant atomic sites in a structure.



- **Self-Interstitials:**

- "extra" atoms positioned between atomic sites.




VACANCY

Vacancy - Missing atom from lattice site.

Sometimes produced during solidification, sometimes by physical factors, (heating, neutrons, working) but present in all crystals.

Usually low in number, but reaches 1 vacancy per 10,000 atoms as temperature rises to melting point.



Vacancy on
silicon surface

Equilibrium Concentration of Point Defects

- Equilibrium concentration varies with **temperature!**

No. of defects $\rightarrow N_v$

No. of potential defect sites. $\rightarrow N$

$$\frac{N_v}{N} = \exp\left(\frac{-Q_v}{kT}\right)$$

Activation energy $\rightarrow Q_v$


Boltzmann's constant $\rightarrow k$

Temperature $\rightarrow T$

(1.38 x 10⁻²³ **J/atom-K**)

(8.62 x 10⁻⁵ **eV/atom-K**)

(depending on units)





Each lattice site is a potential vacancy site

MEASURING ACTIVATION ENERGY, Q_D

We can get Q from an experiment; taking natural logs of both sides....

$$\frac{N_D}{N} = \exp\left(\frac{-Q_D}{kT}\right) \longrightarrow \ln\left[\frac{N_D}{N}\right] = -\frac{Q_D}{k} \frac{1}{T}$$

- Measure N_D as a function of T . Then: Plot $\ln\left[\frac{N_D}{N}\right]$ versus $\frac{1}{T}$



ESTIMATING VACANCY CONC.

- Find the equil. # of vacancies in 1m^3 of Cu at 1000°C .

- Given:

$$\rho = 8.4 \text{ g/cm}^3 \quad A_{\text{Cu}} = 63.5 \text{ g/mol}$$

$$Q_V = 0.9 \text{ eV/atom} \quad N_A = 6.02 \times 10^{23} \text{ atoms/mole}$$

$$\frac{N_D}{N} = \exp\left(\frac{-Q_D}{kT}\right) = 2.7 \times 10^{-4}$$

$Q_D = 0.9 \text{ eV/atom}$ (red arrow pointing to $-Q_D$)
 $kT = 8.62 \times 10^{-5} \text{ eV/atom-K}$ (green arrow pointing to kT)
 $T = 1273 \text{ K}$ (yellow arrow pointing to kT)

For 1m^3 , $N = \rho \times \frac{N_A}{A_{\text{Cu}}} \times 1\text{m}^3 = 8.0 \times 10^{28}$ sites

- Answer:

$$N_D = 2.7 \cdot 10^{-4} \cdot 8.0 \times 10^{28} \text{ sites} = 2.2 \times 10^{25} \text{ vacancies}$$

IMPURITIES IN SOLIDS

Pure metals are difficult to make and not often used.

Gold (is usually alloyed with Cu, Ni, Pt)

24 carat gold = 99.98%-99.95% gold, thus 14 carat = $14/24^{\text{th}}$

Copper (99.99%) is used for for electronics as impurities reduce electrical conductivity.

Pure Platinum is used for thermo-electric applications.

Usually engineering metals are combined with other metals or elements to give ALLOYS. (increased strength, corrosion resistance etc.)

e.g.

STEEL	→	Iron (Fe) + Carbon (C)
BRASS	→	Cu + Zn (zinc)
BRONZE	→	Cu + Sn (tin)
TITANIUM Alloy	→	Ti + 4 Al + 6 V (vanadium)
Ni-Based SUPERALLOYS	→	up to 10 elements

SOLID SOLUTIONS

Simplest alloy is a **SOLID SOLUTION**.

Atoms of Element B are **dissolved** randomly into Element A (host) usually when they are in the liquid state.

"**SOLVENT**" - major element (host)

"**SOLUTE**" - minor element (impurity)

After freezing, they now form a **Solid Solution**.

One phase (all crystals/grains are the same as the next except for orientation i.e. same composition).

e.g.. Liquid solutions - water + alcohol

We can have both:

SUBSTITUTIONAL AND **INTERSTITIAL** SOLID SOLUTIONS


SUBSTITUTIONAL SOLID SOLUTIONS

A host atom is replaced by a different type of atom. The substitutional atom can be either larger or smaller than the host atom but occupies its position. Causes a distortion to surrounding lattice.

INTERSTITIAL SOLID SOLUTIONS

Impurity atoms go into spaces (interstices) between host atoms. Usually spaces are small so interstitial atoms have to be small.


E.g. Hydrogen atoms in iron (from poor welding) - bad
Carbon atoms in iron – deliberate – to produce steel.




Point Defects in Alloys

Two outcomes if impurity (B) added to host (A):


- **Solid solution** of B in A (i.e., random dist. of point defects)



OR



- Solid solution of B in A plus particles of a new **phase** (usually for a larger amount of B)



Second phase particle
--different **composition**
--often different structure.

COMPOSITIONS

In industry usually use weight% for alloys: easier to add 5 kgs of Mg to 10 tonnes of Aluminum than add 4 million atoms of Mg to 67 billion atoms of Al.

$$C_1 = \frac{m_1}{m_1 + m_2} \times 100$$

C_1 is the wt% of element 1 where m_1 and m_2 are the weights of elements 1 and 2.

For chemical/scientific measures often need **atomic %**.

$$C'_1 = \frac{n_{m1}}{n_{m1} + n_{m2}} \times 100 \qquad n_{m1} = \frac{m'_1}{A_1} \qquad (\text{g/g.mol}^{-1}) \rightarrow \text{mol.}$$

n_{m1} is the number of moles of element 1, m'_1 is the mass (grams) and A_1 is the atomic weight of element 1 (g/mole) etc.

Imperfections in Solids

Conditions for substitutional solid solution (S.S.)

- **W. Hume – Rothery rules**

1. Δr (atomic radius) < 15%
2. Proximity in periodic table
 - i.e., similar electronegativities
3. Same crystal structure for pure metals
4. Valency
 - All else being equal, a metal will have a greater tendency to dissolve a metal of higher valency than one of lower valency

A slight difference in size can be tolerated (a slight distortion to lattice), but there is a limit to this, e.g.

	Copper (FCC)	-	Nickel (FCC)	Size%
r =	0.128 nm		0.125 nm	2.3%

Similar electronegativities, valence: Cu: +1, (+2), Ni: +2.

There is 100% solubility between Cu and Ni.

Whereas for Copper and Lead system:

	Copper (FCC)		Lead (FCC)	Size%
r =	0.128		0.175	36.7

There is only 0.1% solubility (only 1 in 1000 atoms can be replaced)

Line Defects

Dislocations:


- are line defects,
- slip between crystal planes result when dislocations move,
- produce permanent (plastic) deformation.



Schematic of Zinc (HCP):

- before deformation



- after tensile elongation





Imperfections in Solids

Linear Defects (Dislocations)


- Are one-dimensional defects around which atoms are misaligned
- **Edge dislocation:**
 - Looks like an extra half-plane of atoms have been inserted into a crystal structure
 - $\mathbf{b} \perp$ to dislocation line
- **Screw dislocation:**
 - spiral planar ramp resulting from shear deformation
 - $\mathbf{b} \parallel$ to dislocation line

Burger's vector, \mathbf{b} : measure of lattice distortion


Dislocations make metals weaker than they should be, **BUT** also allow metals to be deformed (ie. allow plastic deformation). (Chp. 6)

Imperfections in Solids


Edge Dislocation



Screw Dislocation



Imperfections in Solids




0.2 μm

Dislocations
are visible in
electron
micrographs


Dislocations & Crystal Structures

- Structure: close-packed planes & directions are preferred.



- Comparison among crystal structures:
FCC: many close-packed planes/directions;
HCP: only one plane, 3 directions;
BCC: none

- Specimens that were tensile tested.



INTERFACIAL DEFECTS

Defects between crystals or materials

Surface Defects

Material surface: boundary between material and atmosphere. Atomic bonding disrupted. More reactive.

Grain Boundaries (GBs)

Regions where grains (crystals) join. Because adjacent grains (crystals) have different orientations then some disorder at boundaries. Atomic bonding disrupted. GBs are more reactive chemically.

If a solid is made of only one crystal called: Single Crystal


If solid has many Crystals → Polycrystalline.

Most materials/metals are Polycrystalline. i.e. composed of many crystals/grains joined together.

Grain Boundaries in Polycrystalline Materials

Grain Boundaries

- regions between crystals
- transition from lattice of one region to that of the other
- slightly disordered
- low density in grain boundaries
 - high mobility
 - high diffusivity
 - high chemical reactivity





GRAIN BOUNDARIES cont.

Grain boundaries:

- are boundaries between crystals.
- are produced by the solidification process, for example.
- have a change in crystal orientation across them.
- impede dislocation motion.

Schematic






FIGURE 4.8 Demonstration of how a tilt boundary having an angle of misorientation θ results from an alignment of edge dislocations.

BULK/VOLUME DEFECTS

Larger defects such as cracks, pores (holes), other stuff.

These are usually formed or introduced during casting or material fabrication.

They are not really seen as being part of the atomic or crystal structure but as defects introduced during a particular forming process, eg.

- Sand particles from a sand mould during sand-casting.
- Pores (holes/gas bubbles) formed during solidification of molten metal.
- Surface oxide trapped in metal when it is forged

How to observe GRAINS and GRAIN BOUNDARIES

Grains, grain boundaries can be observed in metals/ceramics:


- **Section (cut in half)** and **Grind** sample.
- **Polish** (diamond paste).
- **Etch** (chemical attack) Occurs preferentially depending upon crystal orientation and in grain boundaries.
- **View MICROSTRUCTURE** with microscope.

Can also use: Scanning Electron Microscope, SEM

Can measure properties such as **GRAIN SIZE**. This effects strength, toughness etc.

OPTICAL MICROSCOPY


- Useful up to 2000X magnification.
- Polishing removes surface features (e.g., scratches)
- Etching changes reflectance, depending on crystal orientation.




micrograph of
Brass (Cu and Zn)

Grain boundaries...

- are imperfections,
- are more susceptible to etching,
- may be revealed as dark lines,
- change direction in a polycrystal.



Fe-Cr alloy



(b)

100 μm

Grain Size Determination

Grain size in metals can affect several mechanical properties especially strength. Can measure grain size by:


Intercept method:

- Draw equal length lines randomly across photomicrograph. (l)
- Count number of grains intercepted per line. (n_g)
- Line length is divided by average no. of grains per line (l/n_g)
- This is then divided by magnification of photo to give average grain diameter. $(l/n_g)/M = \text{Avg. g.d.}$

$$\text{Average grain diameter} = \frac{l}{n_g M}$$

Photomicrograph Mag: 100X

7 randomly oriented straight lines labeled, (60 mm long)



Line	No. of grains intersected
1	11
2	10
3	9
4	8.5
5	7
6	10
7	8
AVG	9.1

$$\text{Avg. Grain Dia.} = (l/n_g)/M$$
$$(60/9.1)/100 = 6.59 \times 10^{-2} \text{mm}$$

Grain Size (cont)

- ASTM Grain size Number (n)
- Take photo at 100X and compare with ASTM standard charts of grain size. Each chart shows particular grain size (n). As n increases, grain size decreases. Select chart that is closest match to actual structure.

$$N = 2^{n-1}$$



- where N is the average number of grains per square inch at Magnification X100
- n = ASTM grain size number

Microscopy

Optical resolution ca. 10^{-7} m = 0.1 μ m = 100 nm


For higher resolution need higher frequency

- X-Rays? Difficult to focus.
- Electrons
 - wavelengths ca. 3 pm (0.003 nm)
(Magnification - 1,000,000X)
 - Atomic resolution possible
 - Electron beam focused by magnetic lenses




Scanning Tunneling Microscopy (STM)

- Atoms can be arranged and imaged!



Carbon monoxide molecules arranged on a platinum (111) surface.



Iron atoms arranged on a copper (111) surface. These Kanji characters represent the word "atom".

Photos produced from the work of C.P. Lutz, Zeppenfeld, and D.M. Eigler. Reprinted with permission from International Business Machines Corporation, copyright 1995.

SUMMARY

- **Point, Line, and Area** defects arise in solids.
- The number and type of defects can be varied and controlled (e.g., T controls vacancy conc.)
- **Defects affect material properties** (e.g., grain boundaries control crystal slip).
- **Defects may be desirable or undesirable** (e.g., dislocations may be good or bad, depending on whether plastic deformation is desirable or not.)